


for Qlicksmart Scalpel Blade Remover

MOUNTING BRACKET FITTING TEMPLATE AND INSTRUCTIONS



Bracket as

LOCATE STOP AT BOTTOM

MINIMUM HEIGHT **CLEARANCE**

WARNING

This is not a sterile

Do not mount in a

Only use adhesive as

sole permanent fixing

method when secure

adhesive is achieved.

Replace bracket

when fitting with

Qlicksmart blade

remover is loose.

fixing using the

sterile area.

CONTENTS

- 4 x Screws
- FIXING HOLES 4 x Wall Plugs

device.

WALL MOUNTING

MOUNTING INSTRUCTIONS

- SELECT A MOUNTING LOCATION
 - The Olicksmart blade remover is ideally located near the site of scalpel use or clean-up area.
 - For safety in use, mount bracket as near as practical to elbow height.
 - . Use this template and dotted guide arrows for correct positioning, with minimum height/side clearance
 - . Mounting location must provide stable mounting of bracket and blade remover.
 - **. BEWARE** of concealed wires, pipes & conduits.
- PREPARE MOUNTING SURFACE
 - . Remove any loose or flaking paint.
 - . Clean surface of any oil and grease.
- MARK POSITION OF BRACKET (use this template for correct positioning)
- FITTING (select your surface type: **A** or **B**)

A. FOR CABINETRY, TIMBER OR METAL


B. FOR MASONRY OR HOLLOW WALLS

Adhere bracket with attached adhesive.

If not secure, use suitable fixing screws;

CLEARANCE

Drill holes and secure with suitable fixing screws.




Adhere bracket with attached adhesive.

If not secure, use suitable fixing screws;

Drill holes, insert wall plugs, and secure with suitable fixing screws.

MINIMUM SIDE CLEARANCE MINIMUM SIDE **CLEARANCE**



MINIMUM SIDE CLEARANCE

Bracket as **Bench Mounting**



BENCH MOUNTING

SEE REVERSE FOR WALL MOUNTING INSTRUCTIONS

- SELECT A MOUNTING LOCATION
 - . The Qlicksmart blade remover is ideally located near the site of scalpel use or clean-up area.
 - For safety in use, mount bracket as near as practical to elbow height.
 - . Use this template and dotted guide arrows for correct positioning, with minimum height/side clearance
 - . Mounting location must provide stable mounting of bracket and blade remover.
 - **. BEWARE** of concealed wires, pipes & conduits.
- PREPARE MOUNTING SURFACE
 - . Remove any loose or flaking paint.
 - . Clean surface of any oil and grease.
- MARK POSITION OF BRACKET (use this template for correct positioning)
- FIT WITH ATTACHED ADHESIVE (if not secure use suitable fixing screws)
- FIT WITH SCREWS (if required) (use supplied screws or other fixings as required to ensure a secure mounting)
 - . Cover all exposed threads to prevent injury

For further information on the Qlicksmart scalpel blade remover and Mounting Bracket, contact us at hello@qlicksmart.com, or your preferred local Qlicksmart distributor.

www.qlicksmart.com

WARNING

This is not a sterile device.

Do not mount in a sterile area.

Only use adhesive as sole permanent fixing method when secure fixing using the adhesive is achieved.

Replace bracket when fitting with **Qlicksmart blade** remover is loose.

MINIMUM CLEARANCE FROM BENCH FRONT

Qlicksmart Pty Ltd PO Box 5677, West End, Brisbane, QLD 4101, Australia